

LEAK DETECTORS

Rebuilt

All leak detectors are completely rebuilt in-house and come with our standard 90-day warranty on all parts and labor. Items are subject to availability. Please call for stock.

Varian 936-40



Veeco MS-17



LEAK DETECTORS

MFG	MODEL	DESCRIPTION	PRICE
Alcatel	ASM10	Uses LN ₂ , ALcatel 2004A Mechanical Pump	\$8000.00
Varian	925-20	Uses LN ₂ , Small Tubular Frame, Welch 1400 Foreline Pump	5000.00
Varian	925-40	Porta-test™, No LN ₂ , Hand Truck Cart, One Roughing Pump	6000.00
Varian	936-40	Porta-test, No LN ₂ , Leak Detector Module Only	7500.00
Varian	936-40	Porta-test, No LN ₂ , Cart and 3 cfm Roughing Pump	9500.00
Varian	936-60	Uses LN ₂ , Pneumatic Valves, Two Roughing Pumps	9 - 13000.00
Varian	936-70	No LN ₂ , Pneumatic Valves, Two Roughing Pumps	9 - 13000.00
Varian	947	No LN ₂ , Vacuum Actuated Valves, Two Roughing Pumps, Built-in Helium Leak	15000.00
Veeco	MS-9A	Manual Operation, Visual Indicators, LN ₂ , One Roughing Pump	4500.00
Veeco	MS-9AB	Automatic Operation, Two Roughing Pumps, LN ₂ , Audio Leak Indicator Available on some units	6000.00
Veeco	MS-17AM	Manual Operation, LN ₂ , Two Roughing Pumps	8000.00
Veeco	MS-17AB	Automatic Operation, LN ₂ , Vacuum Actuated Valves, Two Roughing Pumps, Audio Leak Indicator Available on some units	9000.00
Veeco	MS-170	Automatic Operation, LN ₂ , Vacuum Actuated Valves, Two Roughing Pumps, Digital Auto Ranging Leak Box	11000.00
Leybold	Ultratest™ F	Automatic Operation, LN ₂ , Motor Driven Valves, Two Roughing Pumps	8000.00
CEC/DuPont	24-120A	Leak Detector Section Only	4000.00
CEC/DuPont	24-120B	Leak Detector Section Only	5000.00
CEC/DuPont	24-038	Cart and Auto Test Unit	2000.00
CEC/DuPont	24-025	Cart and Auto Test Unit	2000.00
CEC/DuPont	1120HE	Factory Upgrade of 24-120B to Solid State Electronics	6000.00
Balzers	HLT 160	Turbo Pump on Cart with 183 Roughing Pump	15000.00

LEAK DETECTORS

Duniway Stockroom Corp. also offers minor repair, complete refurbishing and calibration services for helium leak detectors.

Call or e-mail us with the manufacturer, model number and a description of the symptoms of the problem to get a RMA (Return Merchandise Authorization) number.

Our customer service representatives will contact you following the inspection to provide you with an estimate for the job.

Repair includes disassembly, cleaning and replacement of required parts. We check sensitivity against calibrated helium leaks which are traceable to NIST.

Varian 936-70



Varian 947

